

Job #: 10.001M
 Job Name: NH-100 Test Fire Dampers

Damper ID #	Location	Test Date	Pass	Fail	Inspected By	Comments	Recommended Solution
FD-1	M-159 (AHU-1 Supply Duct)	3/24/2010	X		Joseph Hale		Replace Access Door
FD-2	Tim Taylor Gym	3/24/2010	X		Joseph Hale		
FD-3	Tim Taylor Gym	3/24/2010	X		Joseph Hale		
FD-4	M-112 (Ech. Duct Thru Floor)	3/24/2010	X		Joseph Hale		
FD-5	M-101 (Below EF-56)	3/24/2010	X		Joseph Hale		
FD-6	M-101 (Below EF-56)	3/24/2010	X		Joseph Hale	Door sticks upon release	Replace Springs/Damper
FD-7	M-103 (Below EF-50)	3/24/2010	X		Joseph Hale		
FD-8	M-103 (Below EF-50)	3/24/2010	X		Joseph Hale		
FD-9	M-102 (Below EF-53)	3/24/2010	X		Joseph Hale		
FD-10	M-102 (Below EF-53)	3/24/2010	X		Joseph Hale		
FD-11	M-102 (Duct AHU-39)	3/24/2010	X		Joseph Hale		
FD-12	M-102 (Duct AHU-39)	3/24/2010	X		Joseph Hale		
FD-13	M-101 (Duct AHU-36)	3/24/2010	X		Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-14	M-101 (Duct AHU-36)	3/24/2010	X		Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-15	M-103	3/24/2010		X	Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-16	M-103	3/24/2010		X	Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-17	M-100 (Duct AHU 37)	3/24/2010	X		Joseph Hale		
FD-18	M-100 (Duct AHU 37)	3/24/2010	X		Joseph Hale		
FD-19	M-100 (Below EF-59)	3/24/2010	X		Joseph Hale		
FD-20	M-100 (Below EF-59)	3/24/2010	X		Joseph Hale		
FD-21	M-104 (Below EF-71)	3/24/2010	X		Joseph Hale		
FD-22	M-104 (Below EF-71)	3/24/2010	X		Joseph Hale	Broken spring on horizontal	Replace spring/Damper
FD-23	M-104 (Duct AHU-32)	3/24/2010	X		Joseph Hale		
FD-24	M-104 (Duct AHU-32)	3/24/2010	X		Joseph Hale		
FD-25	M-106 (Duct AHU-36)	3/24/2010	X		Joseph Hale		
FD-26	M-106 (Duct AHU-36)	3/24/2010	X		Joseph Hale		
FD-27	M-106 (Below Exhaust Fan)	3/24/2010	X		Joseph Hale		
FD-28	M-106 (Below Exhaust Fan)	3/24/2010	X		Joseph Hale		
FD-29	M-107 (Duct AHU-35)	3/24/2010	X		Joseph Hale		
FD-30	M-107 (Duct AHU-35)	3/24/2010	X		Joseph Hale		
FD-31	M-107 (Below Exhaust Fan)	3/24/2010	X		Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-32	M-107	3/24/2010		X	Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-33	M-107 (Below Exhaust Fan)	3/24/2010	X		Joseph Hale		
FD-34	M-105 (Duct AHU-33)	3/24/2010	X		Joseph Hale	No Access Door Installed in Duct	Install Access Door
FD-35	M-105 (Duct AHU-33)	3/24/2010	X		Joseph Hale		
FD-36	M-105 (Below Exhaust Fan)	3/24/2010	X		Joseph Hale		
FD-37	M-105 (Below Exhaust Fan)	3/24/2010	X		Joseph Hale		
FD-38	M-105	3/24/2010	X		Joseph Hale		
FD-39	M-110 (Duct AHU-41)	3/24/2010	X		Joseph Hale		
FD-40	M-205 (Duct AHU-18)	3/24/2010	X		Joseph Hale		
FD-41	M-205 (Duct AHU-18)	3/24/2010	X		Joseph Hale		
FD-42	M-207 (Duct AHU 20)	3/25/2010	X		Joseph Hale		
FD-43	M-207 (Duct AHU 20)	3/25/2010	X		Joseph Hale		
FD-44	M-207 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		

Damper ID #	Location	Test Date	Pass	Fail	Inspected By	Comments	Recommended Solution
FD-45	M-206 (Duct AHU-19)	3/25/2010	X		Joseph Hale		
FD-46	M-206 (Duct AHU-19)	3/25/2010	X		Joseph Hale		
FD-47	M-206 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		
FD-48	M-200 (Duct AHU-21)	3/25/2010	X		Joseph Hale		
FD-49	M-200 (Duct AHU-21)	3/25/2010	X		Joseph Hale		
FD-50	M-200 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		
FD-51	M-202 (Duct AHU-23)	3/25/2010	X		Joseph Hale		
FD-52	M-202 (Duct AHU-23)	3/25/2010	X		Joseph Hale		
FD-53	M-202 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		
FD-54	M-203 (Duct AHU-24)	3/25/2010	X		Joseph Hale		
FD-55	M-203 (Duct AHU-24)	3/25/2010	X		Joseph Hale		
FD-56	M-203 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		
FD-57	M-208 (Duct AHU-17)	3/25/2010	X		Joseph Hale		
FD-58	M-208 (Duct AHU-17)	3/25/2010	X		Joseph Hale		
FD-59	M-209 (Duct AHU-15)	3/25/2010	X		Joseph Hale		
FD-60	M-209 (Duct AHU-15)	3/25/2010	X		Joseph Hale		
FD-61	M-209 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		
FD-62	M-209 (Below Exhaust Fan)	3/25/2010	X		Joseph Hale		
FD-63	M-209	3/25/2010	X		Joseph Hale		
FD-64	M-209	3/25/2010	X		Joseph Hale		
FD-65	M-301 (Duct AHU-12)	3/25/2010	X		Joseph Hale		
FD-66	M-401 (Duct AHU-16)	3/25/2010	X		Joseph Hale		
FD-67	M-401 (Duct AHU-16)	3/25/2010	X		Joseph Hale		
FD-68	Duct AHU-5	3/25/2010	X		Joseph Hale		
FD-69	Room W175-E	3/29/2010	X		Josh Morris		
FD-70	Room W141	3/29/2010	X		Josh Morris		
FD-71	Room W138	3/29/2010	X		Josh Morris		
FD-72	Room W140	3/29/2010	X		Josh Morris		
FD-73	Room W122	3/29/2010	X		Josh Morris		
FD-74	Room W110C	3/29/2010	X		Josh Morris		
FD-75	Room W105	3/29/2010	X		Josh Morris		
FD-76	Corridor Outside Rm. C110 (16x16 Transfer Duct)	3/29/2010	X		Josh Morris		
FD-77	Corridor Outside Rm. C110 (8" Round Duct)	3/29/2010		X	Josh Morris	Visible, But Can't be Reached	Shorten Plenum to within Arm's Reach
FD-78	Corridor Outside Rm. C110 (10x4 Duct)	3/29/2010		X	Josh Morris	Access Door Not Large Enough	Install access door closer to damper
FD-79	Corridor Outside Rm. C112	3/29/2010	X		Josh Morris		
FD-80	Room C110	3/29/2010	X		Josh Morris		
FD-81	Room C109	3/29/2010	X		Josh Morris		
FD-82	Room C110	3/29/2010	X		Josh Morris		
FD-83	Room C110	3/29/2010	X		Josh Morris		
FD-84	Room C119	3/29/2010	X		Josh Morris		
FD-85	Lighthouse Cafe Kitchen	3/29/2010	X		Josh Morris		
FD-86	Room W272	3/29/2010	X		Josh Morris		
FD-87	Room W265	3/29/2010	X		Josh Morris		
FD-88	Room W290	3/29/2010	X		Josh Morris		
FD-89	Room W243	3/29/2010	X		Josh Morris		
FD-90	Corridor Outside Room W254	3/29/2010	X		Josh Morris		
FD-91	Room W223	3/29/2010	X		Josh Morris		
FD-92	Room W224	3/29/2010	X		Josh Morris		
FD-93	Room W208 (Transfer Duct)	3/29/2010	X		Josh Morris		

Damper ID #	Location	Test Date	Pass	Fail	Inspected By	Comments	Recommended Solution
FD-94	Room W208	3/29/2010	X		Josh Morris		
FD-95	Corridor Outside Room WC207	3/29/2010	X		Josh Morris		
FD-96	Room W286	3/29/2010	X		Josh Morris		
FD-97	Room W205	3/29/2010	X		Josh Morris		
FD-98	Room W205-C	3/29/2010		X	Josh Morris	Hard Ceiling with no access door	Install access door in hard ceiling to access damper
FD-99	Room C204 (Above Restroom Door)	3/29/2010	X		Josh Morris		
FD-100	Room C207A	3/29/2010	X		Josh Morris		
FD-101	Room C261 (10" round duct)	3/29/2010	X		Josh Morris		
FD-102	Room C261 (12" round duct)	3/29/2010	X		Josh Morris		
FD-103	Room W203-A	3/29/2010	X		Josh Morris		
FD-104	Room W213	3/29/2010	X		Josh Morris		
FD-105	Room W214	3/29/2010	X		Josh Morris		
FD-106	Room M208 (at floor)	3/29/2010	X		Josh Morris		
FD-107	Room S231	3/29/2010	X		Josh Morris		
FD-108	Corridor Outside S233 (above double doors)	3/29/2010	X		Josh Morris		
FD-109	Room S206	3/29/2010	X		Josh Morris		
FD-110	Room S201	3/29/2010	X		Josh Morris		
FD-111	Corr S 200A Outside M204 (24" round duct)	3/29/2010	X		Josh Morris		
FD-112	Corr S 200A Outside M204 (20" round duct)	3/29/2010	X		Josh Morris		
FD-113	Corridor between Rm. N212 & N213	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-114	Corridor between Rm. N214 & N215	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-115	Corridor between Rm. N216 & N217	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-116	Corridor between Rm. N218 & N219	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-117	Corridor between Rm. N220 & N221	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-118	Corridor between Rm. N222 & N223	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-119	Corridor between Rm. N224 & N225	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-120	Corridor between Rm. N226 & N227	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-121	Corridor between Rm. N228 & N229	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-122	Room N273	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-123	Corridor between Rm. N201 & N202	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-124	Corridor between Rm. N205 & N204	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-125	Corridor between Rm. N205 & N206	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-126	Corridor between Rm. N230 & N231	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-127	Corridor between Rm. N230 & N231 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-128	Corridor between Rm. N232 & N233	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-129	Corridor between Rm. N232 & N233 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-130	Corridor between Rm. N234 & N235	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-131	Corridor between Rm. N234 & N235 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-132	Corridor between Rm. N235 & N236	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-133	Corridor between Rm. N235 & N236 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-134	Corridor between Rm. N255 & N256	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-135	Corridor between Rm. N255 & N256 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-136	Corridor between Rm. N256 & N257	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-137	Corridor between Rm. N256 & N257 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-138	Corridor between Rm. N258 & N259	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-139	Corridor between Rm. N258 & N259 (Thin Floor)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-140	Room N296 (24" round duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-141	Room N296 (18" round duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-142	Room N296 (12x24 duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	

Chamber ID #	Location	Test Date	Pass	Fail	Inspected By	Comments	Recommended Solution
FD-143	Room N296 (44x14 duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-144	Room N294 (36x16 duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-145	Room N294 (16" round duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-146	Room N294 (21" round duct)	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-147	Room N253 Bathroom	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-148	Room N239 Bathroom	3/30/2010	-	-	Josh Morris	Deleted in Renovation	
FD-149	Roof Above Area G (7x16 duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-150	Roof Above Area G (20" round duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-151	Roof Above Area G (18" round duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-152	Roof Above Area G (38x33 duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-153	Roof Above Area G (12x10 duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-154	Roof Above Area G (24x14 duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-155	Roof Above Area G (18" round duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-156	Roof Above Area G (16" round duct)	3/31/2010	-	-	Josh Morris	Deleted in Renovation	
FD-157	Corridor Between Rm. N301 & N302	4/8/2010	X		Josh Morris		
FD-158	Corridor Between Rm. N303 & N304	4/8/2010	X		Josh Morris		
FD-159	Corridor Between Rm. N305 & N306	4/8/2010	X		Josh Morris		
FD-160	Corridor Between Rm. N311 & N312	4/8/2010	X		Josh Morris		
FD-161	Corridor Between Rm. N312 & N313	4/8/2010	X		Josh Morris		
FD-162	Corridor Between Rm. N314 & N315	4/8/2010	X		Josh Morris		
FD-163	Corridor Between Rm. N316 & N317	4/8/2010	X		Josh Morris		
FD-164	Corridor Between Rm. N318 & N319	4/8/2010	X		Josh Morris		
FD-165	Corridor Between Rm. N320 & N321	4/8/2010	X		Josh Morris		
FD-166	Corridor Between Rm. N322 & N323	4/8/2010	X		Josh Morris		
FD-167	Corridor Between Rm. N324 & N325	4/8/2010	X		Josh Morris		
FD-168	Corridor Between Rm. N326 & N327	4/8/2010	X		Josh Morris		
FD-169	Corridor Between Rm. N328 & N329	4/8/2010	X		Josh Morris		
FD-170	Corridor Between Rm. N330 & N331	4/8/2010	X		Josh Morris		
FD-171	Corridor Between Rm. N331 & N332	4/8/2010	X		Josh Morris		
FD-172	Corridor Between Rm. N332 & N333	4/8/2010	X		Josh Morris		
FD-173	Room N342A	4/8/2010		X	Josh Morris	Hard Ceiling with no access door	Install Access Door in Ceiling
FD-174	Room N347A	4/8/2010		X	Josh Morris	Hard Ceiling with no access door	Install Access Door in Ceiling
FD-175	Room N397A	4/8/2010	X		Josh Morris		
FD-176	Room N397A	4/8/2010	X		Josh Morris		
FD-177	Room N397A	4/8/2010	X		Josh Morris		
FD-178	Room N394	4/8/2010	X		Josh Morris		
FD-179	Room N335 (Up Thru Roof)	4/8/2010	X		Josh Morris		
FD-180	Corridor Between Rm. N354 & N355	4/8/2010	X		Josh Morris		
FD-181	Corridor Between Rm. N355 & N356	4/8/2010	X		Josh Morris		
FD-182	Corridor Between Rm. N357 & N358	4/8/2010	X		Josh Morris		
FD-183	Room N358A	4/8/2010	X		Josh Morris		
FD-184	Room N-411	4/8/2010		X	Josh Morris	Ceiling Access Door Blocked by Light	Move Light back off of access door
FD-185	Room N-413	4/8/2010	X		Josh Morris		
FD-186	Room N-414	4/8/2010	X		Josh Morris		
FD-187	Room N-415	4/8/2010	X		Josh Morris		
FD-188	Room N-403	4/8/2010	X		Josh Morris		
FD-189	Corridor Between Rm. N417 & N418	4/8/2010		X	Josh Morris	Access blocked by water pipe & conduit	Move Water Pipes and conduit
FD-190	Corridor Between Rm. N419 & N420	4/8/2010		X	Josh Morris	Access blocked by water pipe & conduit	Move Water Pipes and conduit
FD-191	Corridor Between Rm. N421 & N422	4/8/2010	X		Josh Morris		

Damper ID #	Location	Test Date	Pass	Fail	Inspected By	Comments	Recommended Solution
FD-192	Corridor Between Rm. N423 & N424	4/8/2010		X	Josh Morris		
FD-193	Corridor Between Rm. N425 & N426	4/8/2010		X	Josh Morris	Access blocked by water pipe & conduit	Move Water Pipes and conduit
FD-194	Corridor Between Rm. N427 & N428	4/8/2010		X	Josh Morris	Inaccessible - Access door on top of duct	Move Access door to side of duct
FD-195	Corridor Between Rm. N428 & N429	4/8/2010	X		Josh Morris	Conduit Blocking Access	Move Conduit
FD-196	Corridor Between Rm. N430 & N431	4/8/2010	X		Josh Morris		
FD-197	Corridor Between Rm. N431 & N432	4/8/2010	X		Josh Morris		
FD-198	Corridor Between Rm. N432 & N433	4/8/2010	X		Josh Morris		
FD-199	Corridor Between Rm. N435 & N436	4/8/2010	X		Josh Morris		
FD-200	Corridor Between Rm. N437 & N438	4/8/2010	X		Josh Morris		
FD-201	Corridor Between Rm. N439 & N440	4/8/2010	X		Josh Morris		
FD-202	Corridor Outside N444-A	4/8/2010	X		Josh Morris		
FD-203	Corridor Outside N-407 (Stair Side)	4/8/2010		X	Josh Morris	Access door tabs are bent	New Access door
FD-204	Corridor Outside N416	4/8/2010	X		Josh Morris		
FD-205	Corridor Outside N445	4/8/2010	X		Josh Morris		
FD-206	Corridor Outside N446	4/8/2010	X		Josh Morris		
FD-207	Corridor Outside N446	4/8/2010	X		Josh Morris		
FD-208	Corridor Outside N446	4/9/2010	X		Josh Morris		
FD-209	Corr S-100 (12x12 Above Double Door)	4/9/2010	X		Josh Morris		
FD-210	Corr S-100 (8" Above Double Door)	4/9/2010	X		Josh Morris		
FD-211	Rm. W129	4/9/2010	X		Josh Morris		
FD-212	Rm. W151	4/9/2010	X		Josh Morris		
FD-212	Corridor Outside Rm C108	4/9/2010	X		Josh Morris		
FD-213	Rm. S112	4/9/2010	X		Josh Morris		
FD-214	Corr S-152 Outside M-105 (20" Round)	4/9/2010	X		Josh Morris		
FD-215	Corr S-152 Outside M-105 (22" Round)	4/9/2010	X		Josh Morris		
FD-216	Corr S-152 Outside M-105 (40x18 Duct)	4/9/2010	X		Josh Morris		
FD-217	Rm. C126	4/9/2010	X		Josh Morris		
FD-218	Rm. C126	4/9/2010	X		Josh Morris		
FD-219	Rm. C138 (24x18 Transfer Duct)	4/9/2010	X		Josh Morris		
FD-220	Rm. C138	4/9/2010	X		Josh Morris		
FD-221	Rm. E107 (6" round)	4/9/2010	X		Josh Morris		
FD-222	Rm. E107 (8" round)	4/9/2010	X		Josh Morris		
FD-223	Corr. Outside E 110 (12x6 Duct)	4/9/2010	X		Josh Morris		
FD-224	Rm. E112 (12x12 duct)	4/9/2010	X		Josh Morris		
FD-225	Rm. E112 (36x12 Transfer Duct)	4/9/2010	X		Josh Morris		
FD-226	Rm. E112 (6" round Duct)	4/9/2010	X		Josh Morris		
FD-227	E Lobby (24x16 Duct)	4/9/2010	X		Josh Morris		
FD-228	Rm. E159 (14x8 Duct)	4/9/2010	X		Josh Morris		
FD-229	Rm. E156 (14x8 Duct)	4/9/2010	X		Josh Morris		
FD-230	Rm. E161 (22x12 Duct)	4/9/2010	X		Josh Morris		
FD-231	Rm. E161 (16x8 Duct)	4/9/2010	X		Josh Morris		
FD-232	Rm. E161 (16x8 Duct)	4/9/2010	X		Josh Morris		
FD-233	Rm. E161 (20x12 Duct)	4/9/2010	X		Josh Morris		
FD-234	Rm. E162	4/9/2010	X		Josh Morris		
FD-235	Rm. E162	4/9/2010	X		Josh Morris		
FD-236	Rm. E162	4/9/2010	X		Josh Morris		
FD-237	Rm. E165	4/9/2010	X		Josh Morris		
FD-238	Rm. E165	4/9/2010	X		Josh Morris		
FD-239	Rm. E165	4/9/2010	X		Josh Morris		
FD-240	Rm. E166	4/9/2010	X		Josh Morris		



Assessment ID	Building Code	Floor Code	Room Code	Location	Deficiency	Recommendation	Notes	ID Date	Unit Cost	Qty	Total Cost	Funding Source
90055	CAMP LJ	02	M201	Mechanical Equipment Room #8	The space between the pipe & floor is not filled with appropriate FRR material	Repair the opening with appropriate FRR material	6 vertical penetrations in slab.					
90056	CAMP LJ	02	W205A	Exam room	Pipes penetrating FRR wall assembly not filled with appropriate FRR material	Fill penetration with appropriate FRR material.	1 Penetration					
90057	CAMP LJ	02	W205B	Tumor Reg Waiting	Pipes penetrating FRR wall assembly not filled with appropriate FRR material	Fill penetration with appropriate FRR material.	1 PenetrationL					
90058	CAMP LJ	02	C200B	In corridor at double doors.	Pipes penetrating FRR wall assembly not filled with appropriate FRR material	Fill penetration with appropriate FRR material.	1 Penetration					
90059	CAMP LJ	02	C200B	In corridor at double doors.	Life safety defec other than those enumerated in sections 1 thru 6 (see notes)	Correct deficiency	Need exit sign.					
90060	CAMP LJ	02	M208B	Jan. closet	Door has an undercut of $\geq 3/4$ {NFPA 80: 1-11.4.} {LSA 1C.5}	Replace door or install compliant door sweep.	> 1" undercut.					
90061	CAMP LJ	02	C261	At double doors in corridor.	Duct penetration not protected by approved smoke damper	Install Damper as per code	2-12" duct with no dampers.					
90062	CAMP LJ	02	Stair-9	Penthouse	The space between the pipe & floor is not filled with appropriate FRR material	Repair the opening with appropriate FRR material	4 vertical penetration in slab.					
90063	CAMP LJ	02	C264E	In corridor at double doors.	Pipes penetrating FRR wall assembly not filled with appropriate FRR material	Fill penetration with appropriate FRR material.	3 Penetrations					
90064	CAMP LJ	02	N261	Vestibule	Door is not positive latching {NFPA 80: 2-4.4.3} {LSA 1C.2}	Repair/replace door to insure positive latching.	Adjust.					
90065	CAMP LJ	02	N200A	In corridor by N206	Not visable from any direction of access {LSC 7.10.1.2*} {LSA 5K.1}	Install new or remove obstruction	Remove Exit sign.					
90066	CAMP LJ	02	N200C	In corridor over the double doors.	Air duct penetrating FRR wall assembly not filled with appropriate FRR material	Fill penetration with appropriate FRR material.	Seal around cable tray.					